


NOTES:

1. Material: Aluminum 5052-H32. Please notify if this alloy is not appropriate for the tapped holes.
2. If tapped holes require thicker material, please contact us with recommended thickness.
3. Do not countersink threaded holes on the front face--all threads are required.



PROJECT			
OP			
TITLE			
Elevator mounting plate v1.2.2			
APPROVED	SIZE	CODE	DWG NO
CHECKED	B		
DRAWN Michael Biggs 10/29/2020	SCALE 1:2	WEIGHT	SHEET 1/1